



PILOT BOARDING DEFICIENCY REPORT

DATE: 11/8/2020 TIME: 1800

VESSEL: MSC Melissa

MASTER:

PILOT: M. P. Haley

CONDITIONS: Light airs low swell

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
- ☐ COMBINATION LADDER
- ☒ SIDE PORT
- ☐ OTHER

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☒ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

Paint on stepping surface of ladder steps.

- ☐ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Signature: _____

MASTER (if available)

PILOT