

## PILOT BOARDING DEFICIENCY REPORT

DATE: 2 12 21 TIME: 0700
VESSEL: Fairchem Blade
MASTER:
PILOT: Daniel Sullivan
CONDITIONS: Clear
APPLICABLE LADDER ARRANGEMENTS (check all that apply):
PILOT LADDER ONLY COMBINATION LADDER SIDE PORT OTHER
DEFICIENCIES (check all that apply and provide brief comment)
GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)
PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)
COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)
MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)
DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)
ADDITIONAL REMARKS:
Ladder was sewred to deck rings using only 318" synthetic
line. Customarily shackles are used to secure the ladder to the
deck rings. When I questioned the officer a mile disembarking he said "Shackles
are against company policy"
ignature:
MASTER (if available) PILOT



