

DEPARTMENT OF HOMELAND SECURITY
U.S. Coast Guard
PORT STATE CONTROL REPORT OF INSPECTION - FORM B

MISLE Activity Number:
6810090
Exam Type:
Admin

In accordance with IMO Port State Control Procedures and the International Ship & Port Facility Security (ISPS) Code)

1. Reporting Country: United States of America

2. Name of Ship: **MSC PAOLA**

3. IMO Number: **9161297**

4. Date of Inspection: **17 SEP 19**

5. Place of Inspection: **SEC NY**

6. Nature of Deficiency¹

No.	Code	Description	Cite (Convention)	(Action Taken) ²
01	10101	ALL ARRANGEMENTS USED FOR PILOT TRANSFER SHALL EFFICIENTLY FULFILL THEIR PURPOSE OF ENABLING PILOTS TO EMBARK AND DISEMBARK SAFELY. UPPER PLATFORM OF PORT SIDE ACCOMADATION LADDER ATTACHED USING LOOSE BOLTS AND ROPE MAKING IT UNSAFE TO BOARD VESSEL ON PORT SIDE ACCOMADATION LADDER.	74 SOLAS 14 V/2.1	40AC

Copy provided to: **Capt. Santosh Kumar Gupta**
(Printed name of Master/Vessel representative)

Signature



Name of PSCO: **MS12 ORI MARTINEZ**
(Printed name of duly authorized PSCO of reporting authority)

Signature

Issuing Unit Name and Address:
U.S. COAST GUARD SECTOR NEW YORK
212 COAST GUARD DRIVE
STATEN ISLAND, NY 10305
(718) 354-4348

Copies forwarded to: Check as appropriate

- ☐ Agent ☐ Ship Management
☐ Flag State ☐ Recognized Organization
☐ Recognized Security Organization

Reviewed by Supervisor

Name:

Date:

¹ This inspection was not a full survey and deficiencies listed may not be exhaustive. In the event of a detention, it is recommended that a full survey is carried out and all deficiencies are rectified before an application for re-inspection is made.

² Codes for action taken, see below: (Note: code numbers are derived from international harmonization, U.S. uses similar codes and those are reflected below.)

10	Deficiency Rectified	17	Rectify deficiencies prior to departure	20	Ship expelled
15	Rectify deficiencies by next port	60	Rectify deficiencies prior to movement	25	Ship denied entry
16	Rectify deficiencies within 14 days	40	Rectify deficiencies prior to next US port after sailing foreign	a.	To the satisfaction of RO/RSO
50	Rectify deficiencies within 30 days	30	Ship detained	b.	To the satisfaction of the Administration
				c.	To the satisfaction of the Coast Guard