



PILOT BOARDING DEFICIENCY REPORT

DATE: ¹⁰9/22/2020 TIME: 1200
VESSEL: YM Mandate
MASTER: _____
PILOT: M. P. Haley
CONDITIONS: Light airs low swell fog

APPLICABLE LADDER ARRANGEMENTS (check all that apply):

- ☐ PILOT LADDER ONLY
☒ COMBINATION LADDER
☐ SIDE PORT
☐ OTHER _____

DEFICIENCIES (check all that apply and provide brief comment)

- ☐ GENERAL ARRANGEMENT (ie: Insufficient lighting, no officer, unsafe deck access, etc.)

- ☐ PILOT LADDER (ie: Poor condition/wear, not resting on hull, poor rigging, etc.)

- ☒ COMBINATION LADDER (ie: Poor condition/wear, not secured, platform too low, etc.)

Non compliant Trap door configuration

- ☐ MAN ROPES (ie: Poor condition/wear, incorrect diameter, poor rigging, etc.)

- ☐ DOCKSIDE (ie: Gangway condition/pitch, netting, poor rigging, etc.)

ADDITIONAL REMARKS:

Ladder not secured to height of handrail. Ladder not resting against hull.

Ladder not through the trapdoor. Gangway not secured to hull.

Signature: _____

MASTER (if available)

PILOT





